

Cross section of surface-micromachined high-pressure sensor







Figure 2 Longitudinal and transverse stress distribution along radius of a circular diaphragm.



metallization.



Polysilicon Pressure sensor: thermistor 8 polysilicon resistors




Multi-diaphragm configuration:

- minimize self-heating effect
- make layout much easier


Wheatstone bridge

アアア





Calibration curve of the sensor (T = 40 °C)  $\vdash$  /  $\leftarrow$  7

Step-up anchor: caused by




Cross section of sensor diaphragm






contact holes, and Al metalization

(mask #5 and #6)




F/G 11



4

不平



FIGIS